



Dimensions



PIN assignment



Range adjustment

S1	Output
● → Switch On	5 6
0–10V	●
0–20mA	●
4–20mA	● ●

S1	Input
● → Switch On	1 2 3 4
PT100, 3-wire	
PT100, 2-wire	●
-50 – 50°C	
-50 – 100°C	●
-50 – 150°C	● ●
0 – 100°C	● ●
0 – 150°C	● ● ●
0 – 200°C	● ● ●
0 – 300°C	● ● ●
0 – 400°C	● ● ● ●

